


PSU Supplemental


For products shipped without a battery, after unpacking insert a CRP2 manganese dioxide lithium battery, 6V 1400mAh. These batteries are commonly used in photography equipment.







➤ If the PSU-2 matching the above referenced image, is being replaced by the below referenced image, please see the reversed side of this document for wiring the new PSU-2.

PSU-2 New Design



➤ Setup A menu has changed. With the change in design of the new PSU, the result is an additional output can be configured for additional application functionality. Please use our Installation Operation Manual 00-02-0697 for the setup configuration.





MANUFACTURING, SALES & ENGINEERING 2151 RANDON DYER ROAD ROSENBERG, TX 77471

SALES, SERVICES & SUPPORT 4646 S HARVARD AVE TULSA, OK 74135 DOMESTIC SALES & SUPPORT FW MURPHY PRODUCTS PHONE: 918 957 1000 EMAIL: INFO@FWMURPHY.COM WWW.FWMURPHY.COM

FW MURPHY CONTROL SYSTEMS & SERVICES PHONE: 281 633 4500 EMAIL: CSS-SOLUTIONS@FWMURPHY.COM INTERNATIONAL SALES & SUPPORT LATIN AMERICA & CARIBBEAN PHONE: +1918 770 8775 EMAIL: INTERNATIONAL@FWMURPHY.COM



FM 668933 (Rosenberg, TX - USA)



